


120 VOLT POWER
SOURCE REQUIRED



WIRING DIAGRAM

HEATED VACUUM VENT